SCURVEAIR CLARIFIED WIRING DIAGRAM